


Head Voltage 100
Temperature 29
X Caliper 165.25

Tue Feb 13 00:17:35 2007

LS Spectrum

Depth: 150.2



Firmware Vers 4.0
Receive err 55552
Time out err 23816
Overruns 0

SS Spectrum

Depth: 150.2

